

PT-100

# **Posing Table**

**ASSEMBLY INSTRUCTIONS** 



## **Parts List**

- 1 tabletop
- $1-3/8" \times 1"$  hex head screw
- 2-1/8" x 3/8" screws
- 1 mounting bracket
- 4 1/4" x 1/2" screws
- 1 pneumatic cylinder
- 1 locking knob
- 1 pedestal base
- 5 casters (or glides)

# Step One

Remove all the parts from the carton and make certain you have all the items in the parts list above and in the correct quantity.

#### **Step Two**

Insert the casters (glides) into the pedestal base. Be sure all casters are inserted securely.

## **Step Three**

Attach the mounting bracket to the pneumatic cylinder using the 3/8" hex head screw and the two 1/8" x 3/8" screws. Firmly tighten all screws.

#### Step Four

Using the four 1/4" screws, fix the mounting bracket to the table top. Tighten all four screws securely.

#### Step Five

Push the pneumatic cylinder down onto the pedestal base until it is secure.

#### Step Six

Adjust the table top to your desired height and tighten the locking knob.

Make certain all screws are tightened fully before using this posing table.